

Urban Park progress photos 2021

Photographs:



Photograph looking Westwards across site from 20-21 entrance. Drainage/gully connection excavation in progress (hand dig).



Photograph looking Westwards across site from 20-21 entrance. Drainage works and general progress shown



General progress photograph.



General progress – View North from Carlton St Vehicular gate.